FIELD INSPECTION REPORT

	f Inspection: 03/12/2020 District: Samazlebur	- 144
Divisio	n: Dalsinghsarai Length (km): 1.00	
	of the Road: UMDR Singlin to Kumhar Tila	
	e/Programme: MAINTENANCE	
	ge No.; of the Project: Ongoing/Completed/Under Maintenance	
	The state of the s	
ŠI/No.	Programme and All Control of the Con	T PHOTO COLOR
20 100 100		Romani
1.	Payement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)-	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3,	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4:	Compliance History	
a)	Status of ATR's & any others	Yes

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	CON
Unsatisfactory (U)	- N L

(Signature)

NAME: Manangy Kuronar

DESIGNATION: Azet Engineer