

FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	Begusarai
Division :	TELMHRA	Length (km):	2.030 km
Name of the Road:	Chhabilapur P.W.D. Road to MILKE		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/BE/TELM/19/0005	Road Id No.:	32010501020
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No S.D.B.C
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No Walk done
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	N.R.
a)	Status of ATR's & any others	N/E

Overall Rating :

Satisfactory (S)	✓	'S'
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

Grin
(Signature)

03/12/2020

h
Ach
31/12/20

NAME: UMESH KUMAR MAHTO
DESIGNATION: JUNIOR ENGINEER