FIELD INSPECTION REPORT

Date of I	nspection:	2/12/2020	District: Begasaras Length (km): chta R. e. o Road to M	•
Division	: Techno	71.7	Length (km):	- soute
Name of	the Road: M	okhi harpur A	offer R. e. o Road to N	Unopus Maria
Scheme/	Programme.	THE STATE OF THE S		
Package	No.: RM/BE	1786/19/0003	Road Id No.: 320/050/	750
Status of	the Project:	Ongoing/Completed/	n aradation/ Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance				Remarks
Sl. No.		Parameters to be checked		
1.	Pavement			SAL LINE
a)	Road Junction condition			S/U HA
b)	Condition of Surfacing			S/U NA
	Riding Quality			S/U NA
c)				S/U NA
d)	Road Camber Whether free from defects such as visible cracks, exposed			Yes/No NA
e)	aggregates in case of CC Pavement.			
n	Contraction Joints provided or not (CC Pavement)			Yes/No H
g)	Compaction of flank/slope & raincuts if any			Yes/No MA
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U A A
c)	Condition of railings/slab/approach for Bridges			S/SRI/U MA
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No Y
4.	Compliance History			
a)	Status of ATR's & any others			
				NA
Overall 1	Rating :	Satisfactory (S)		'B1
			requires Improvement (SRI)	
		Unsatisfactory (U		

work not started

Artoinal Stranger (Signature) J. E

NAME: Artified Charme

DESIGNATION: J. 6