

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Begusarai
Division : TELDHARA	Length (km): 0.590 km
Name of the Road: NH-28 to Chiranjipur Bhaul	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BE/TEL/19/0009	Road Id No.: 32010502027
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	L/S/U
b)	Condition of Surfacing	L/S/U
c)	Riding Quality	L/S/U
d)	Road Camber	L/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	L Yes/No
f)	Contraction Joints provided or not (CC Pavement)	L Yes/No
g)	Compaction of flank/slope & raincuts if any	L Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	L Yes/No
4.	Compliance History	N.R.
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Gm 03/12/2020
(Signature)

NAME: UMESH KUMAR MAHTO

DESIGNATION: JUNIOR ENGINEER