

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: ARWAH
Division : ARWAH	Length (km):
Name of the Road: NH 98 to hichchan baha via Agnoos.	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10603108014 on going
Status of the Project: On going /Completed/ <u>Under Maintenance</u>	Under maintenance
Work is a case of: New Connectivity/Up gradation/ <u>Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/NoX
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Lal Bahadur Prasad

10/03/2020
(Signature)
A E