

FIELD INSPECTION REPORT

Location : District : Bhagalpur		
Length (Km) : 10.22 Km		
Name of the Road : - Nathnagar Tamhansai to Kayrele		
Scheme / Programme : MAINTENANCE ✓		
Package No. : Road Id No. : 20703208223		
Status of the Project : Ongoing / Completed / Under Maintenance ✓		
Work is a case of : New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1.	Pavement	✓
a)	Road Junction condition	S / U
b)	Condition of Surfacing	S / U
c)	Riding Quality	S / U
d)	Road Camber	S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓ Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall Rating :		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI) ✓	
	Unsatisfactory (U)	

NAME :

DESIGNATION :

Abhinav
4/12/20
J.E.

(Signature)

4/12/20
(अभिनाव. जे.)
4. 8.