

FIELD INSPECTION REPORT

		111111111111111111111111111111111111111	and the state of t		
Date of Inspection: 02 12 2020 District: Patra.					
Division: Patora / Sampat drak. Length (km): 3.650 km.					
-	the Road: 3	shail Pongsy se	Parsa sampatchala Poncy	sy Path.	
	rogramme:	MAINTENANCE			
Package		,054) 2016 -2017			
	the Project:		/Under Maintenance		
Children to the control of the contr			rs to be checked Remarks		
	Pavement				
a)	Road Junction	\$			
b)	Condition of Surfacing			3	
c)	Riding Quality			S	
d)	Road Camber			2	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			res	
g)	Compaction of	Yes			
2,6	Cross Drains	ge	A REPORT OF THE PARTY OF THE PA	and the section of the	
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges			2	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance	History -			
a)	Status of ATI	R's & any others		200	

Overall Rating

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	3
Unsatisfactory (U)	10.5. ·

Supery 9 12/20 (Signature)

NAME: SUPPITA RANF

DESIGNATION: DP. RWD (w) Subdivision Sampatelak.