

FIELD INSPECTION REPORT

Date of Inspection :- 3.12.2020 District :- Nalanda
 Division :- Rajgir Length (km) :- 3.800 k.m
 Name of the Road :- Repair of Amirganj R.C.D road to Banauli.
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: - 10200908054.
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance **Maintenance**

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its paring	S SRI (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI (NA)
c)	Condition of railings slab approach for Bridges	S SRI (NA)
3.	Road Furniture	
a)	Whether sign boards informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No (SRI)
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Rampreesh Kumar

NAME:

SE
Rajgir

3/12/2020
 (Signature) Rajgir