

# FIELD INSPECTION REPORT

|                                                                         |                                            |
|-------------------------------------------------------------------------|--------------------------------------------|
| Date of Inspection : 3.12.2020                                          | District: Kaimur                           |
| Division : Mohania                                                      | Length (km): 16.20                         |
| Name of the Road: Repair of Road from Lahurpatti to NH-30 to Chaurasiya |                                            |
| Scheme/Programme:                                                       | MAINTENANCE                                |
| Package No.:                                                            | Road Id No. ✓                              |
| Status of the Project:                                                  | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                                      | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                         | Remarks       |
|---------|------------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | Pavement                                                                                                         | ✓             |
| a)      | Road Junction condition                                                                                          | S/U           |
| b)      | Condition of Surfacing                                                                                           | S/U           |
| c)      | Riding Quality                                                                                                   | S/U           |
| d)      | Road Camber                                                                                                      | S/U           |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                     | Yes/No        |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                 | Yes/No        |
| g)      | Compaction of flank/slope & raincuts if any                                                                      | Yes/No        |
| 2.      | Cross Drainage                                                                                                   | ✓             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                             | S/SRI/U       |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                         | S/SRI/U       |
| c)      | Condition of railings/slab/approach for Bridges                                                                  | S/SRI/U       |
| 3.      | Road Furniture                                                                                                   |               |
| a)      | Whether sign boards/informatory/cautionary Board/km. & stones/Pavement road markings are provided and maintained | 200m Yes/No ✓ |
| 4.      | Compliance History                                                                                               |               |
| a)      | Status of ATR's & any others                                                                                     | NO            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

4/10/20  
3.12.20  
(Signature) J P

NAME: Rohan Prasad Gubla