

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Buxar
Division : Dumaraon	Length (km): 3.750 km.
Name of the Road: NH84 to Garahatha Kafa	
Scheme/Programme:	MAINTENANCE MR-3054
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Completed</i>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N-A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Handwritten signature
3/12/20
I. E.
Brahmabhus

(Signature)

NAME:

DESIGNATION: