

FIELD INSPECTION REPORT

Date of Inspection : 3/12/22	District: Nalanda
Division : Rajgir	Length (km): 3.09 km
Name of the Road: Side Par to Donidih	
Scheme/Programme: MAINTENANCE (3054 MR)	
Package No.: Batch RM/NA/RAJ/19/0002	Road Id No.: 10200905002
Status of the Project: Ongoing	Ongoing Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA) ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA) ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA) ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (NA) ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Rampresh Kumar
NAME: SE
Rajgir

3/12/22
(Signature) SE