

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Munger
Division : Munger	Length (km): 1.400
Name of the Road: NH80 Visaynagar to Rishi Kund	
Scheme/Programme: MAINTENANCE	MR - old
Package No.:	Road Id No.: - 20803708156
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others - सुड़के लाका 100m में पंचायत हस्त से जल नाला जोड़ना के द्वारा पाइप बिछाने के दौरान कच्चा रोड़ा गमाया गया जिससे Repair नहीं करीया गया है।	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ravi Shankar Mandal

J.E.

NAME:

Randap
02.12.2020
(Signature) J.E.