

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020 District : Munger
 Division : Munger Length (km) : 1.000
 Name of the Road : Chureula Bridge to Krishi Vigyan Kendra via Sugaulan Bridge
 Scheme/Programme : MAINTENANCE MR-old
 Package No. : Road Id No. : -20803708173
 Status of the Project : Ongoing Completed Under Maintenance
 Work is a case of : New Connectivity/Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/S/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/N/A
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of AFR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

✓S/

Ravi Shankar Manday
 J.R.

NAME:

Ramdas
 03.12.2020
 J.R.
 (Signature)