

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: Nalanda
Division : Raigir	Length (km): 2.580 km.
Name of the Road: Bihar Raigir road se nahu nonhi gram tak	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10200908043
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (NA)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No (SRI)
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ramporewesh Kumar
SE
NAME: Raigir

102
2/12/2020
SE
(Signature)