FIELD INSPECTION REPORT

Date of Ir	nspection: 3	112 12020	District: Nalamda		
			ength (km): 4.050 Km·		
Name of the Road: Bihar exampler Path se wa miso via karantighe Jozapin.					
Scheme/Programme: MAINTENANCE Five yeurs.					
Package No.: Road Id No.: 10200908044					
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Rond Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No/HA	
g)	Compaction of flank/slope & raincuts if any			Yes/No /	
2	Cross Drainage				
a)	Condition of fical waits in traine pipe curvers are purely			s/skvu	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRVU	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance	History	,	S. 1944	
a)	Status of AT	R's & any others		ATR	

Overall Rating

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	V

(Signature)

NAME: SHIVE frough fulle

DESIGNATION: A - E