

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: SAHARSA	
Division : R.W.D. WORKS DIV. SAHARSA		Length (km): 1.05 Km	
Name of the Road: Repair of Road from Benidaha. to China Rite mi/			
Scheme/Programme: MAINTENANCE		Road Id No.: 20904308098	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts H.A.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges H.A.	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	

Signature
03.12.2020
(Signature) J.E

NAME: J. E. Kumar
Junior Engineer.