

# FIELD INSPECTION REPORT

|                        |                                            |              |        |
|------------------------|--------------------------------------------|--------------|--------|
| Date of Inspection :   | 03.12.2020                                 | District:    | Supaul |
| Division :             | TRIVENIGANJ                                | Length (km): |        |
| Name of the Road:      | Repair of road Devipatti to Sakhua.        |              |        |
| Scheme/Programme:      | MAINTENANCE                                |              |        |
| Package No.:           |                                            | Road Id No.: |        |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |        |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |        |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                      |              |
| a)      | Road Junction condition                                                                                              | ✓<br>S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓<br>S/U     |
| c)      | Riding Quality                                                                                                       | ✓<br>S/U     |
| d)      | Road Camber                                                                                                          | S/U          |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No N.A.  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No N.A.  |
| g)      | Compaction of flank/slope & rainents if any                                                                          | Yes/No N.A.  |
| 2.      | <b>Cross Drainage</b>                                                                                                |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓<br>S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓<br>S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | ✓<br>S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓<br>Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |              |
| a)      | Status of ATR's & any others                                                                                         |              |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME:  
Surendra. Pd. & h.  
7/5

(Signature)  
3/12/20