

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020		District: Katihar
Name of Road:		Repair of Kaiwariya Bastaul - Sanauli PWD Road to Vainu Road
Scheme/ Programme:	MAINTENANCE (MR 3054)	
Package No.	Road ID No. 21105708027	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	Yes
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	Yes
c)	Condition of railings/slabs/approach for Bridges	Yes
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	Yes
4	Compliance History	
a)	Status of ATR & any others	No

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: SATISH CHAUDHARY
 Designation: AE, Prantpur
 RWD, (W) Division Manihari

Satish 02/12/2020
 (Signature)