## FIELD INSPECTION REPORT (Lahladpur)

Date o	f Inspection: 0	3-12-2020	District: SARAN	-21	
Division: chapya-2			Length (km): 1.0 km		
		pair of road from	kataiya Bazar main road to Rrath	mik Urdu mak	
Scheme/Programme: MAINTENANCE			Road Id No.:	Laskant	
Packag		Ongoing/Completed			
			ew Connectivity/Up gradation/ Maintenance		
SI. No.	WINDS TO SECURITY OF THE SECURITY OF	Parameters to	THE SECOND WAS INCOMED AND ADDRESS OF THE PARTY OF THE PA		
1941.1.1				Remarks	
. 1	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			_8/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SPI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			Market State of the State of th	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	istory			
a)	Status of ATR's	s & any others		All the second s	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	381

Signature)

NAME:

**DESIGNATION:**