

FIELD INSPECTION REPORT

Date of Inspection :	4.12.2020	District:	SARAN
Division :	MARHAURA	Length (km):	3.10 km
Name of the Road:	Repair of road from Kanya vidyalaya to Anandpur tarapur Road to Pansurambur Gaudan Dam via Gosi Anandpur.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31306508026
Status of the Project:	Ongoing/Completed/Under Maintenance Completed		
Work is a case of:	New Connectivity/Up-gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing <i>up to 1 km length road surface good.</i>	S/U SRI
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Remark:-

up to 2.00km Road Surface damage due to flood & heavy rain. At three points road cut in length approx. 5m, 30m, 20m length. Road is now motorable condition in breach area.

(Signature) *4/12/2020*

NAME:

Devendra Kumar
A.E.

DESIGNATION: