

FIELD INSPECTION REPORT

Date of Inspection: 04/12/2022		District: Sonbhadra
Division: RWD Noida/12		Length (km): 1.2 km
Name of the Road: Belhara - Lilaipura - KESH-73 to 500m pda Bridge Gaudipura		
Scheme/Programme: MAINTENANCE		Package No.: 01/11-2022
Status of the Project: Ongoing/Completed/Under Maintenance		Road Id No.: 31306540029
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating

1

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)

NAME: P. Mohan
 DESIGNATION: JS