

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 10.70 KM (Baliyachauk to Keshapur)
Name of the Road: Balaur Haat to Keshapur	7.15 KM transfer to RCD
Scheme/Programme: MAINTENANCE (3054 MRD)	3.25 KM Balance
Package No.:	Road Id No.: 31507208127
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition (Due to widening of NH-77 Road Junction is covered)	✓S/✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	.
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Bijendra Kumar
03.12.2020
JE/Kurhan

K. Anshu
03/12/20
AE
RWD/Kurhan