FIELD INSPECTION REPORT

| Date of Ir | spection: | 3/12/2020 Distr | ict: muzsffax pur | and manufactured the same of t | |
|---|--|------------------------|----------------------|--|---|
| Division : | m429.f. | habur east-2 Long | th (km): 3.25 km | | |
| | the Road: e | 194 MUKK PYZKLALA | to wality indust | cet roat | |
| | Programme: | | R 3054) | | |
| Package No.: Road Id No.: | | | | | |
| | the Project: | Ongoing/Completed/Unde | | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | | | ı | |
| Sl. No. | Parameters to be checked Remarks | | | | |
| 1. | Pavement | | | | |
| a) | Road Junction condition | | | √ś/U | , |
| b) | Condition of Surfacing | | | √Ś/U | |
| c) | Riding Quality | | | ~\$/U | |
| d) | Road Camber | | | √S/U |] . |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No | | | HA | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No | MA |
| g) | Compaction of flank/slope & raincuts if any Yes | | | Yes/No | floome portion floomkdama dua to floo |
| 2. | Cross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI | | | S/SRI/U | NA |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U | NA |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U | NA . |
| 3. | Road Furniture | | | | |
| a) | | | | Yes/No | |
| 4. | Compliance History | | | NA | |
| a) | Status of ATR's & any others | | | NA. | |
| | Some | postion of road dam | reduc to overtobline | Clark water | - 202-1 |

Overall Rating :

| 8 | 7 1000 00000 |
|---|--------------|
| Satisfactory (S) | (5) |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Gignature) Gignature)

NAME: GANESH KUMAL

DESIGNATION: JUNIOR ENGINEER.

Scanned with CamScanner