

FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District:	Vaishali
Division :	Harihar	Length (km):	1.0 km
Name of the Road:	Mansuwan Dahan to Mansuwan		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	S S
c)	Riding Quality	S S
d)	Road Camber	S S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes No
g)	Compaction of flank/slope & raincuts if any	✓ Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab/approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S) S
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)


(Signature)

NAME:

DESIGNATION: