

FIELD INSPECTION REPORT

Date of Inspection :	9/12/20	District:	Vizianagaram
Division :	H2: PPA	Length (km):	7.20 Km
Name of the Road:	Chakravarthy to Kunturam Jerry Ramesh to David Nagar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓
f)	Contraction Joints provided or not (CC Pavement)	✓
g)	Compaction of flank/slope & raincuts if any	✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S) S
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

[Signature]
 9/12/20
 Signature

NAME:

DESIGNATION: