

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Vaishali
Division :	Hajipur	Length (km):	7.50 km
Name of the Road:	महाराष्ट्र में वसतिगृह के लिए		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓
f)	Contraction Joints provided or not (CC Pavement)	✓
g)	Compaction of flank slope & raincuts if any	✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings slab approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards, informative, cautionary, Board km & 200m, stones, Pavement road markings are provided and maintained	Yes No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

SRI

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Signature

NAME:

DESIGNATION: