

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Rohtas.
Division : R.W.D Bikanernagar	Length (km): 1.38 km.
Name of the Road: Sanjauli - chaita Bahori	
Scheme/Programme: MAINTENANCE	new policy 2018
Package No.:	Road Id No.:
Status of the Project:	☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance
Work is a case of:	☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ram chis Singh

(Signature) R Singh
02/12/20
A.E