

FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020 District: Madhubani
 Division: Benipatti Length (km): 7.25 km
 Name of the Road: Hissar to Sukhwasi
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 31910008052
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S
b)	Condition of Surfacing	✓S
c)	Riding Quality	✓S
d)	Road Camber	✓S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓S/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRT
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRT
c)	Condition of railings/slab approach for Bridges	✓S/SRT/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Not any

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

U

NAME: R.K. Bhagat, A-E
 Md Sani - J-E
 DESIGNATION:

Signature
 03/12/20
 J-E