

FIELD INSPECTION REPORT

Date of Inspection :	03/12/20	District:	Patna
Division :	Patna Sahibpur	Length (km):	4.35 km
Name of the Road:	NH-30 Nandlal Chhapra to Mauoharpur Kachhura.		
Scheme/Programme:	MAINTENANCE - sys maintenance.		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance - 3054 WR (-2017-2018)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance - sys maintenance.		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	S.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes.
4.	Compliance History	
a)	Status of ATR's & any others	1. at ch. 800 Rec- put Required intended 2. - Road in 1.15km badly damaged by Buidco for namami ganga project 3. - Remaining length badly damaged by Flood 4. - Road Maintenance not possible by routine maint.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Note: - 1700 m Flood damaged and maintained by emergency work. & 1.15 km having Namami Ganga project in progress by Buidco.

NAME:

DESIGNATION:

(Signature)