## FIELD INSPECTION REPORT

ate of In	spection: 03/12/207	District: Nalande	
ivision:	Blot Oil a calca	1 I annth (km)	
ame of t	he Rond: Repair of and	d from Sarmera Issua to Brindawa	n mad
	s Se wining. I tat vella l 121	AVIACE	
ackage l	Vo.;	Road Id No.:	
Vork is a		Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance  Sl. No. Parameters to be checked		Remarks	
1.	Pavement	include to be entired	
a)	Road Junction condition		SIU
b)	Condition of Surfacing		ร์กบ
c)	Riding Quality		√s/U
d)	Road Camber		√S/U
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		SISRIAU
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
. 3.	Road Furniture		
a)	Whether sign boards/ stones/Pavement road	Yes/No	
A.	Compliance History		
a)	Status of ATR's & any	others	No

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mojib Ahmad

DESIGNATION: J.F.

Scanned with CamScanner