

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Patna	
Division : Paligay		Length (km): 1.30km	
Name of the Road: Ben High to Bara Bara			
Scheme/Programme: MAINTENANCE			
Package No.: RM/PAL/19/001		Road Id No.:	
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance			
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/✓
b)	Condition of Surfacing		S/✓
c)	Riding Quality		S/✓
d)	Road Camber		S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	yet to be done	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	yet to be done	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

JE
03/12/2020
JE

JE
03/12/2020
A S

(Signature)
EE
03.12.20

NAME: