

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Madhubani
Division : Phulparas		Length (km): 12.95
Name of the Road: Chharapatti to Laukeshi Mahadev Math to Rajarampatti Nagihia Road SH Ch. 0.00 to 12.95		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31909900810
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. CC Pavement not provided	Yes/No -
f)	Contraction Joints provided or not (CC Pavement) CC Pavement Not Provided	Yes/No -
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage Cross Drainage Not provided	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: JITENDRA KUMAR
DESIGNATION: Asst. Engineer

(Signature) 03/12/2020

467
03/12/20
58