FIELD INSPECTION REPORT

Date of Inspection: 04, 12, 2020			District: Madhybani	
Division: Phupanas			Length (km): 9.15 km	
Name of	the Road:	Kariaut t	- Amchini	
	Programme:	MAINTENANCE	- Mincroso	
Package			Road Id No .: 1 190990	0813
			/Under Maintenance	
THE REAL PROPERTY.	a case of:	New Connectivity/L	p gradation/ Maintenance	
SI, No.		Parameters to	be checked	Remarks
1	Pavement			
n)	Road Junction condition			S/Ú
b)	Condition of Surfacing			S/U
c)	Riding Quality			SALL
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage (nos) nainage nos provides			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			3.0
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
1	Compliance I	Hetory	(日) 法国 (中)	TEN CARTOE

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

DESIGNATION: A.E. DATIH 2020
AE

Oh. J. C.

Status of ATR's & any others