

FIELD INSPECTION REPORT



Date of Inspection :	3/12/2020	District :	Bhagalpur
Division :	Kahalgaon	Length (Km) :	2.17
Name of the Road:	Ekdara To Mathurapur Shivnarayanpur PMGSY Path (Kahalgaon)		
Scheme / Programme	MAINTENANCE		
Package No. :		Road Id No. :	20703400828
Status of the Project :	Under Maintenance		
Work is a case of :	Maintenance		

Sl. No.	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	Yes
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	2
Satisfactory but Improvement (SRI)	-
Unsatisfactory (U)	-

Name :



 (Signature)