

FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020		District: NALANDA	
Division : HARNAUT		Length (km): 1.000	
Name of the Road: CHERO NACHARNAUSA ROAD TO SIRSI			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	200m	✓Yes/No
4.	Compliance History		
a)	Status of A/R's & any others		

Overall Rating :

Satisfactory (S)	(3)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)