

FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA - 2	Length(Km):	7.10 km.
Name of Road:	NH-105 DARIMACHOWK TO KEDTI VIA CHAKBHAWAN - TAK		
Scheme/Programme:	Maintenance (MIR)		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing of plain cutting road and gully points	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	✓ Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	✓ S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	✓ S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating: S			

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

HARERAM

Designation:

J.E.

2.12.2020

J.E.

(Signature)
02.12.2020