FIELD INSPECTION REPORT

| Date of Inspection: 03.12.2020 | | | District: Patra | | |
|--|--|--------------------|--|---------------------------------------|--|
| Division: Patra | | | Length (km): 1.00 | | |
| | | 1-30 to Bariarpo | | | |
| | Programme: | MAINTENANCE | D 111No. | | |
| | | 019-20/PATNA/64 | Road Id No.: | | |
| Status of the Project: Ongoing/Completed Work is a case of: New Connectivity/U | | Ongoing/Completed/ | gradation/ Maintenance | | |
| alebratien and a street court and and | | L. (400) | The state of the s | Remarks | |
| Sl. No. | | Parameters to l | be checked | i i i i i i i i i i i i i i i i i i i | |
| 11. | Pavement | | | | |
| a) | Road Junction condition | | | S/U | |
| b) | Condition of Surfacing | | | √S/U | |
| c) | Riding Quality | | | √8/U | |
| d) | Road Camber | | | √S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No NA | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/Nona | |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No | |
| 2. | Cross Draina | ge | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | 、S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/UNA | |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U~A | |
| 3. | Road Furniture | | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No | |
| 4. | Compliance History | | | | |
| a) | Status of ATR's & any others | | | NO | |
| Overall | Rating . | Surfaceing | work completed, her wo | ik in prog! | |
| O TOTAL | | Satisfactory (S) | | 5 | |

| surfacely work completed, Kest w | rock in progra |
|---|----------------|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Himanshu Raj DESIGNATION: Assistant Engineer_