

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020		District: Rohas	
Division: R.W.D-Bikramganj		Length (km): 1.620 KM	
Name of the Road: T02 TO Arisia			
Scheme/Programme: MAINTENANCE		New Maintenance Policy 2018	
Package No.:		Road Id No.: 10301102101	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance		Policy 2018	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing	up to W.B.M Gr-III	✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	TO Be done	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No only board
4.	Compliance History		
a)	Status of ATR's & any others		N

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Akhileshwar Prasad

Prasad
02/12/2020
(Signature)

TO
be
done