

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Rohtas
Division : R.W.D - Bikramganj	Length (km): 1.810 KM
Name of the Road: TD2 TO - Karaundi	
Scheme/Programme: MAINTENANCE	New maintenance policy 2018
Package No.: -	Road Id No.: 1030/102/103
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
f)	Contraction Joints provided or not (CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	TD Be done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No only board
4.	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Prasad
02.12.2020
(Signature)

NAME: Akhileshwar Prasad