(9)

FIELD INSPECTION REPORT

12 20	District: Patau.
sampat chak.	Length (km): 2/10 Km.
Nayachak	to Kachuara Road.
MAINTENANCE	
(3054)	Road Id No.:
Ongoing/Completed	/Under Maintenance _
New Connectivity/Up gradation/ Maintenance	
֡	MAINTENANCE (3054) Ongoing/Completed

S1. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	8
b)	Condition of Surfacing	S
c)	Riding Quality	8
d)	Road Camber	\$.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	8
f)	Contraction Joints provided or not (CC Pavernent)	\$.
g)	Compaction of flank/slope & raincuts if any	\$.
2.	Cross Drainage	ALTE
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NIA
. 3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	300 M Au

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

subujer 10.

(Signature)

NAME: SUPFIYA PANI

DESIGNATION: AE, RCOD(co) subdivision.
Sampat chak.