

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Kaimur
Division : Bhabua		Length (km): 2.40km
Name of the Road: Hatta Mahesh road to Chand via Jamal pur Palei		
Scheme/Programme: MAINTENANCE		
Package No.: MR (3054)	OK	Road Id No.: 1030/400827
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	✓ S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

MK
02.12.20
(Signature)

NAME: Mukesh Kumar
DESIGNATION: JE