FIELD INSPECTION REPORT

Date of I	nspection: 3	5/17/20	District: Conya	The second secon
Division: Tukan			Length (km): 6.001 m	
		ulvichak to Ran	nsishewa mahadovhoth Ro	shusar figh
Scheme/	Programme:	MAINTENANCE	10	
Package			Road Id No.:	
		Ongoing/Complete	ed/Under Maintenance	
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			⊗ Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/S			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4	Compliance History			
a)	Status of ATR's & any others			_
Overall	Rating :	Satisfactory (S) Satisfactory but Unsatisfactory (requires Improvement (SRI)	SRE

NAME:

Scanned with Cam

(Signary Tolean'