

FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020 District: East Champaran
 Division: Pakri dyal Length (km):
 Name of the Road: phenhara to mushar toli part - II
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: ☒ Ongoing ☒ Completed ☐ Under Maintenance
 Work is a case of: ☒ New Connectivity ☒ Upgradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S ☐ U
b)	Condition of Surfacing	☒ S ☐ U
c)	Riding Quality	☒ S ☐ U
d)	Road Camber	☒ S ☐ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank slope & raincuts if any	☒ Yes ☐ No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S ☐ SRI ☐ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S ☐ SRI ☐ U
c)	Condition of railings/slab/approach for Bridges	☒ S ☐ SRI ☐ U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes ☐ No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

W
03.12.2020
(Signature)

NAME: Dharmendra Kumar
 03.12.2020
 DESIGNATION: JE