

(Work Under Progress)

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Rohtas
Division :	R.W.D. - Biskramganj	Length (km):	3.0 Km
Name of the Road:	NH-30 To Ghelaur		
Scheme/Programme:	MAINTENANCE	New maintenance policy 2018	
Package No.:	—	Road Id No.:	10301305029
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition (upto WBM)	✓ S/U
b)	Condition of Surfacing (upto WBM) (1.0km)	✓ S/U
c)	Riding Quality upto WBM (1.0km)	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Work in Progress
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	In Progress Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No To Be done
4.	Compliance History	
a)	Status of ATR's & any others	No.

In Progress

To be done

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Akhileshwar Prasad

Prasad
02.12.2020
(Signature)