

FIELD INSPECTION REPORT

Date of Inspection : 2.12.20	District: Kaimur
Division : Bhabhua	Length (km): 5.250
Name of the Road: Bhabhua - coalhanta road to Thingai Bihra via Kosi	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/2019-20/11	Road Id No.: 10301401004
Status of the Project:	Ongoing/Completed/Under Maintenance <i>profile correction</i>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U <i>✓/✓</i>
b)	Condition of Surfacing	S/U <i>✓/✓</i>
c)	Riding Quality	S/U <i>✓/✓</i>
d)	Road Camber	S/U <i>✓/✓</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>✓/✓</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>✓/✓</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>✓/✓</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>✓/✓</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>✓/✓</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>✓/✓</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Kumar
2.12.20
(Signature)

NAME: *Siddhanta Kumar*

DESIGNATION: T.O.