

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020.		District : GAYA	
Division : Neemichak Bahani ; Sub Division - Manpur		Length (Km.) : 0.80 Km.	
Scheme/Programme : M/R-3054		MAINTENANCE Gaya Khijar Sarai to Delha Road (Class-II)	
Package No : N/A		Road Id No. : N/A	
Status of the Project : Ongoing		Ongoing/Completed/Under Maintenance	
Work is a case of : Maintenance		New Connectivity/1p gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement Work Not Started yet.		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & rain cuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in. Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 250m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work Not Started yet.

03/12/2020
A.E.R.W.D.
Manpur.