

FIELD INSPECTION REPORT

Date of Inspection :		District : GAYA	
Division : Neenachak Bathani		Length (Km.) : 2.40 Km.	
Scheme/Programme: M/R-3054		MAINTENANCE <i>Gaya Khijar Sarai to Village Bijubigha Nanauk Road.</i>	
Package No. : N/A		Road Id No. : N/A	
Status of the Project : <i>Ongoing</i>		Ongoing/Completed/Under Maintenance	
Work is a case of: <i>Maintenance</i>		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	<i>Pavement Work Not Started Yet.</i>		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	<i>Cross Drainage</i>		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3	<i>Road Furniture</i>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	<i>Compliance History</i>		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SR1)	
Unsatisfactory (U)	

Work not started yet.

03/12/2020.
A. E. R. W. D.
Manpur.