

FIELD INSPECTION REPORT

Date of Inspection: 03.12.2022	District: ARWAL
Division: ARWAL	Length (km): 2.000
Name of the Road: BAIDRABAN BELKHARA WITH NEAR TWA TO HAIBATPUR PATH	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10603100821
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of bank/slope & ruts/cuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRTT
b)	Condition of Abutment & Wing walls/Slab in RCC culverts.	✓SRTT
c)	Condition of railings/slab approach for Bridges	✓SRTT
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Road sign & 200m stones/Pavement road markings are provided and maintained.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRT)

Unsatisfactory (U)

5

[Signature]
(Signature)

[Signature]
S. Singh
N. Singh