

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020
 Division : ARWA4
 District : ARWA4
 Length (km): 2.700
 Name of the Road: BAIDRA BAD BELKHARA PATH TO RAMPUR CHAURAM PATH.
 Scheme/Programme: MAINTENANCE
 Package No.:
 Road Id No.: 10603100824
 Status of the Project: Ongoing/Completed/Under Maintenance Under maintenance
 Work is a case of: New Connectivity/Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	✓ U
c)	Riding Quality	✓ U
d)	Road Camber	✓ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI U
c)	Condition of railings/slab approach for Bridges	✓ SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Signature
 NAME:

3/12/2020
 (Signature)