

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	ARWAJ
Division :	ARWAJ	Length (km):	0.85 km
Name of the Road:	Kaler Basi Masjid to Budhan Bigha Path,		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10603100834
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Under Maintenance</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d) *	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>N/A</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>N/A</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>N/A</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>Partially</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>N/A</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>N/A</i>
3.	Road Furniture	
a) *	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>Yes</i>
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Lal Bahadur Prasad

(Signature) *[Signature]*
02/12/20
A E